00T 1 8 1-13

Mr. Rod Kimbro
Solid Waste & Spill Response Unit
Enforcement & Field Operations
Division
Texas Department of Water Resources
P. O. Box 13087 - Capitol Station
Austin, Texas 78711

Dear Mr. Kimbro:

Please find enclosed the following hazardous waste site inspection forms completed by Ecology and Environment.

- (1) TX00884 Shell Oil Co.-Deer Park
- (2) TX07731 East Texas Gas Plant Tyler
- (3) TX07811 Texaco Production Midland
- (4) TX08451 Hess Oil & Chemical Corp.-Pt. Isabel(5) TX09881 Uniroyal Chemical-Pt. Nueches
- (6) TX09971 Precision Mational Corp.-Waco
- (7) TX10197 Protective Coatings, Inc.-Houston (8) TX10201 Galveston Co. LF/BFI-Hitchcock

Should you have any questions regarding this matter, please contact Anthony Gardner at 214-767-6421.

Sincerely.

NULCHES BUTHUL PRODUCTS CO.

TXD 008 063 414

Samuel L. Nott, Chief Enforcement Section

Enclosures

bcc: Hazsit Files

6AW-SE: Newman: 10-18-83

SUPERFUND FILE

SEP 1 1 1992

REORGANIZED